

GOVERNMENT OF ARUNACHAL PRADESH
OFFICE OF THE ASSISTANT ENGINEER CAPITAL SUB DIVISION-3/A
PWD AR, ITANAGAR

No. CSD-3/A/W-13/2024-25

Dated Itanagar the 31st May 2024

FITNESS CERTIFICATE

To be filled by the Inspecting Officer: Assistant Engineer (Civil)

1	Name of the Officer	:-	Er. JUMMY TABA
2	Name of the School/Institute	:-	VIVEKANANDA RESIDENTAIL PUBLIC SCHOOL
3	Location with Name of Education District/Sub-District	:-	VIVEK VIHAR NEAR DNGC ITANAGAR
4	Classification of Building as specified in Column 4 of the application for fitness certificate and size	:-	G+2 RCC Building
5	Period for which the certificate is issued	:-	1 (one) year from date of issue of the certificate
6	Nature of defects, if any		
	(a) Foundation and basement	:-	NIL
	(b) Superstructure	:-	NIL
	(c) Doors and Windows	:-	NIL
	(d) Wood Woork Wrought & put up	:-	NIL
	(e) Roof	:-	NIL
	(f) Flooring	:-	NIL
	(g) Miscellaneous (Cracks, etc)	:-	NIL
7	Any Major Defects noticed which will render the building unsafe in any manner	:-	NIL
8	Whether maintenance works have been done properly	:-	YES
9	Whether the structure is sound or not for conducting classes	:-	Yes sound for conducting classes

Note: - 1 The stability of the structure should be examined also with reference for location, altitude, intensity of wind, exposure of flood etc. (2) Any additional observation if deemed necessary for the certificate may be furnished separately with this certificate.

CERTIFICATE


Certified that the school building was inspected by me on 31/05/2024 and found to be fit to conduct classes for the period of 1 (one) year for the reason stated above.

Place:- Itanagar
Date:-31/05/2024

Assistant Engineer
Capital Sub Division-3/A
PWD AR, Itanagar

Chairman
Vivekananda Res. Public School
Itanagar, A.P

Principal
Vivekananda Res. Public School
Itanagar, A.P



OFFICE OF THE ASSISTANT ENGINEER
CAPITAL SUB DIVISION-3/A PWD AP
ITANAGAR

No. CSD-3/AW-13/2024-25/ 233

Dated Itanagar the 28/08/2024

BUILDING SAFETY CERTIFICATE

To be filled by the Inspecting Officer: Assistant Engineer (Civil)

1	Name of the Officer	:-	Er. JUMMY TABA
2	Name of the School/Institute	:-	Vivekananda Residential Public School
3	Location with name of Education District/Sub-District	:-	VivekVihar, Itanagar, Arunachal Pradesh
4	Classification of Building as specified in Column 4 of the application for fitness certificate and size.	:-	1. G+2 RCC Building (Block-2)
5	Period for which the certificate is issued	:-	1 (One) Year from date of issue of the certificate
6	Nature of defects, if any	:-	NIL
	a) Foundation and basement	:-	NIL
	b) Superstructure	:-	NIL
	c) Doors and Windows	:-	NIL
	d) Wood work wrought and put up	:-	NIL
	e) Roof	:-	NIL
	f) Flooring	:-	NIL
	g) Miscellaneous (Cracks, etc.)	:-	NIL
7	Any major defects noticed which will render the building unsafe in any manner	:-	NIL
8	Whether maintenance works have been done properly	:-	Yes
9	Whether the structure is sound or not for conducting classes.	:-	Yes sound for conducting classes

Note:- 1. The stability of the structure should be examined also with reference for location, altitude, intensity of wind, exposure of flood etc. (2) Any additional observations if deemed necessary for the certificate may be furnished separately with this certificate.

CERTIFICATE

Certified that the school building was inspected by Er. Benyi Dulom, Junior Engineer, on 28/08/2024 and as per report submitted, the building is found to be fit to conduct classes for the period of 1 (one) year for the reason stated above.

Place:- Itanagar

Date :- 28/08/2024

Chairman

Vivekananda Res. Public School
Itanagar, A.P

Principal

Vivekananda Res. Public School
Itanagar, A.P

Assistant Engineer,
Capital Sub-Division 3/A
PWD AP, Itanagar